




electric drill spare parts list

No.	Part Name	Qty	No.	Part Name	Qty
1	Drill chuck	1	22	Field coil Sleeve	1
2	Output shaft	1	23	Motor housing	1
3	Woodruff key 4*5*13	1	24	Insulating strip	2
4	Check ring for hole $\phi 40$	1	25	Brush holder	2
5	Oil sealing ring	1	26	Carbon brush	2
6	Bearing 6203	1	27	Brush holder cover	2
7	Check ring for shaft $\phi 17$	1	28	Assist handle	1
8	Screw	4	29	Rear handle	1
9	Head shell	1	30	Screw M8*25	1
10	Big Gear	1	31	Switch	1
11	Check ring for shaft $\phi 12$	1	32	capacitor 0.22 μ F	1
12	Bearing 608	4	33	Screw ST4*14	5
13	Gear shaft	1	34	Cable clamp	1
14	Woodruff key 3*3.7*10	1	35	Left handle	1
15	Driven wheel	1	36	Right handle	1
16	Check ring for shaft $\phi 10$	1	37	Labeling	3
17	Middle cover	1	38	Screw M5*20	4
18	Bearing 6200	1	39	Cabel sheath	1
19	Armature	1	40	Cable plug	1
20	Screw ST5*60	2	41	Hex wrench	1
21	Field Coil	1	42	Tension spring	1